

Furniture Photo Report

HOL/119

B12

Admin Area Holmfirth HOL
Type Gate/Other
Grid Reference SE12690910

Survey Date 13/02/2007
Condition Satisfactory



IMG_4804.jpg